

Set task information

Engineering brief

Your engineering organisation is interested in quality assurance.

You have been asked to review a drawing and the production data to try to understand why issues have been occurring during the production of a turned component.

The component will be manufactured in batches of 100 and is made of titanium.

The drawing for the component is shown below.

